

Weekly Local Navigation Warning Summary Monday 14 October 2024

WAITEMATA HARBOUR

Waitemata - The Whau River no.6 lit beacon (Q.R) int no. 3837.1 has been reported as missing. Mariners are advised to exercise caution when navigating in the area.

Waitemata - The Northcote Mooring area SE Port hand beacon in charted position 36° 49.64S 174° 45.37E has been temporarily positioned at 36° 49.60S 174°45.33E. Final position will be advised in due course.

MANUKAU HARBOUR

Manukau - The Tokaroa Point starboard beacon (Fl.G.4s) Int no. 4110.07 has been reported as destroyed. A temporary green buoy is reported to be in its place. Mariners are advised to navigate with caution in the area.

CANCELLED NAVIGATION WARNINGS

Kawau Bay – The beacon between Algies Bay and Goldsworthy Bay has been reinstated with a North Cardinal beacon (a Notice to Mariners will be issued in due course for the chart correction).